



Motorola Tablet Xoom 2 USB Port Repair

REPAIR ON MOTOROLA MZ617 USB PORT GUIDE

Written By: Abu Zubair



INTRODUCTION

2 issues:

bricked battery and

USB port lifted on the MZ617

both now answered in a video I just uploaded below.

Direct charging batteries, reinforcing with Loctite Chipbonder helps with lifted USB port.

Z.

[video: <https://www.youtube.com/watch?v=h4HJvOhQ9qo>]

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-08-11 12:35:47 PM.